
AL BRAZE BUTT JOINT FAILURE TEST



6061-T6: All surfaces "tinned", joined and filleted then air cooled after brazing.